



REPORT SNO 5061-2005

Rehabilitation of the DTD-Canal in Vrbas

Assessment of the Environmental
Status, Pollution Sources, and
Abatement Measures



Industrial effluents are discharged untreated via I-64 lateral into the DTD-Canal